



Inspect and Check

Take no chance Inspect the scaffold set up after erection and do it every day while scaffolding in use. Do not remove or allow removal of any bracing till the work is over

Begin with good footing

Use proper baseplate, sills or footers (or in combination) on solid ground make sure the scaffold is leveled or plumbed well

Reject Damage Scaffolding

Any part of the scaffolding pipe is Bend shall be rejected and kept aside for repair no adjustments to be made and used

Tie Scaffolding to the Building

Scaffolding should be tied to the structure using heavy wire or tie-in devices the first vertical tie should be at the minimum height 4 times the narrowest base dimensions. Additional ties are not to exceed 26 feet vertically maximum & horizontal distance between ties is not to exceed 30 feet.

CAUTION

Avoid Buying from Traders / Agents Confirm by Visiting the Factory

Do not over load Scaffolding.

Use metal Catwalks, Platforms

Buying NEW Scaffolding

Factory Visit is compulsory in order to check the manufacturing practices being followed by the manufacturer ie, from of welding, pipe cutting process, dies and Fictures etc.



Full body safety Belt is compulsory while on scaffolding and must be anchored to fixed structure